

copy
APPROVED
DEC 20 1961
[Signature]
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Artesia
Lease No. LC 068823-C
Unit **RECEIVED**

JAN 4 1962

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

30-015-01(54)

October 26, 1960

Well No. 10 Welch Unit is located 1650 ft. from [N] line and 1650 ft. from [E] line of sec. 20
NE 1/4 section 20 26 27E NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Welch (Delaware) Eddy New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to a total depth of 2227 feet. The following cement plugs were set: 2180-2130; 1527-1475; 1425-1375; 340-300; 0-10. Steel marker erected, pits leveled and location is ready for inspection.

RECEIVED
OCT 27 1960
[Signature]

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. M. C. Ritchie
Address Box 953
Midland, Texas

By [Signature]
Title Agent