


## ARTESIA OFFICE COPY

Budget Bureau 42-R358.2  
Approval expires 12-31-52(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office

Lease No. 10 065736-A

Unit



## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

*This well was not drilled at the location shown*

30-015-01161

4-12-58

19

Well No. 1 is located 23 ft. from S line and 41 ft. from E line of sec.N 1/4 of SE of 29  
(1/4 Sec. and Sec. No.)29S  
(Twp.)77E  
(Range)New Mexico  
(Meridian)Glenn County  
(Field)544  
(County or Subdivision)New Mexico  
(State or Territory)The elevation of the derrick floor above sea level is 3199 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Put 8 sack cement plug in bottom of hole and 2 sack plug in top with regular pipe marker. Left all casing in hole, did not attempt to pull.

*72 883  
6 1/2" csg 883 2/15/54  
6 1/2" csg 883 8-16-883  
Hole was dry for 20 ft to 21 ft*

ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Buck Jones Drilling CompanyAddress McGuire, Texas

By

Title

*Buck Jones*  
*Operator*