

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

30-015-03738

Land Office _____

Lease No. **LC0720100**Unit **LC 072010-1**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____, 19 **55**

Ashland

Well No. **1** is located **1900** ft. from **{N}** line and **1900** ft. from **{E}** line of sec. **22**

SW/4 Section 22 **24s** **30E** (Meridian)

(1/4 Sec. and Sec. No.) (Twp.) (Range)

N. C. **Eddy County** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned per notice of intent as follows:

10 rods at TD of 1043'

10 rods at 2574' base of salt

10 rods at 1830

10 rods at base of 175' 10 3/4" pipe

10 rods at surface - marker set

Pit and bottom plugs

Cleaned location

RECEIVED
FEB 20 1959U. S. G. S.
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **J. Glen Bennett**Address **105 W. Illinois****Midland, Texas**By *J. Glen Bennett*

Title _____