Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		C S Form C-103 Revised 1-1-89	F N
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVATIO P.O. Box 20 Santa Fe, New Mexico	88	WELL AP! NO. 30-015-04744 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 0G5725	
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESEF (FORM C	CES AND REPORTS ON WE POSALS TO DRILL OR TO DEEPER WOR. USE "APPLICATION FOR PE 101) FOR SUCH PROPOSALS.)	NOR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
OL WELL X GAS WELL - 2. Name of Operator J. RAY STEWART 3. Address of Operator P. O. BOX 451, MIDLA	OTHER	Contesia di	POKER LAKE STATE 8. Well No. 1 9. Pool name or Wildcat SUL CORRAL-CATYON (DELAWARE)	
4. Well Location Unit LetterM : 664 Section 8	Township 25S R	Line and 667	Feet From The WEST 9610 NMPM EDDY Cour	Line
11. Check A NOTICE OF INT	10. Elevation (Show whether KB-3199.5' Appropriate Box to Indicate ENTION TO:	Nature of Notice, Re		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE		
OTHER: 12. Describe Proposed or Completed Operations work) SEE RULE 1103. WORK DONE: PLEASE SEE	ions (Clearly state all pertinent details, an		TO SALT-WATER DISPOSAL	X
I hereby certify that the information above in true is sionature TYPE OR PRINT NAME J. RAY STE	and complete to the best of my knowledge and	Delief.	DATE DATE 3- 11-99 TELEPTIONE NO687-10	186.
(This space for State Use)	W Gum GGX	Pintiets	DATE 6.16.99	

WORK DONE:

11/18-20/98

POH rods & tubing, test and replace 3 joints tubing, ran bit and scrapper to TD, no fill, perfs clean, ran tubing with packer to test casing, found holes at 588' and 680'-690', ran cement bond log, good cement surface to 300' and 690' to 3690' (TD=3692'), no cement 300' to 690'.

11/23 to 12/1/98

Set BP at 3600', dump 5 sx sand, set cement retainer at 700', SQ casing 150 sx to 600#, DO cement, retainer etc. to TD, test 425# 1 minute but slowly leaked-off (588' hole still leaking), SQ 72 sx to 680#, SI with 400# on casing, DO cement to TD, test 300# for 15 minutes, ran production tubing and packer to 3600', circulate packer fluid, test casing annulus to 300# and leaked, POH, reran workstring and packer, test casing, found leak again at 588', POH.

12/7 & 8/98

Ran 2 $3/8" \ge 5 1/2"$ plastic coated production packer set at 3600' with on-off tool, POH workstring, reran with test packer set at 3445', test production packer to 1000# OK, POH with test packer, reran workstring to 651', circulate 130°F water 4 hours, SQ 588' hole with 153 gallons Howco Permaseal to 350#, SI 48 hours at 265#.

12/10/98

POH tubing, reran with notched collar, DO plug, circulate hole with treated annular fluid, POH tubing, reran 2 3/8" plastic coated production tubing, latch into production packer, work air out of annulus, ran OCD test with chart, held 300# for 30" OK (Gary Williams witnessed).

12/30/98 - 2/15/99

Installed SWD facilities equipment and began SWD 2/15/99.