



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Las Cruces

Land Office

LC-061616-B

Lease No.

M

Unit

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 10, 1963

Well No. 1 is located 660 ft. from S line and 660 ft. from E line of sec. 9
SW/4 of Sec 9 25 S 30 E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Corral Canyon Pool Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3241.2 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On February 18, 1963, perforated zones 3621-24' and 3788-97', was given an additional sand frac treatment. Zones were treated with 15,000 pounds of sand and 5,000 gallons refined oil. Swabbed back frac and load oil. Ran 3762' of 2-3/8" O.D. 4.7 # EUE Tubing. Installed pump.

CORRECTED COPY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Fred Pool Drilling Company

Address %Ralph H. Viney

713 First National Bank Bldg

Midland, Texas - 79704

By

Ralph H. Viney

Title Agent