



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 067601

Unit _____

RECEIVED
FEB 7 1961O. C. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of Plugging</u> X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 23, 1960

Richardson & Bass)
Well No. 1 is located 660 ft. from S line and 660 ft. from E line of sec. 7
SE/4 24S 31E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Eddy County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3534 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

September 16, 1959

- 1st. Plug - 25 sz. from 4184' - 4274'
2nd. Plug - 25 sz. - 90' cement on top of salt or base of Rustler. 850' - 940'.
3rd. Plug - 20 sz. or 60' in base of surface

Steel cap with 4" drill pipe bearing location description standing upright from well. Drill pipe encased with cement at base - November 23, 1960. Cement base 2' X 2' X 18".

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ambassador Oil CorporationAddress 3101 Winthrop Ave.Fort Worth, Texas.P.O. Box 260 - Artesia, N.M.

By _____

Title District Superintendent
Artesia, New Mexico