

(SUBMIT IN TRIPLICATE)

Land Office

LC 067324

Lease No.

Unit

RECEIVED

JAN 23 1961

O. D. D.
ARTERIAL OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
COPY

30-018-05862

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal

May 11

60

Well No. 1-15 is located 660 ft. from XXXX line and 660 ft. from XXXX line of sec. 15
SW/4 SW/4 Unit M Sec. 15 26-S 31-E NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Eddy New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

May 11, 1960 Pumped 35 sacks of cement across Delaware formation from 4154' to 3969', 20 sacks at 1972' and 20 sacks at 762'. Marker cemented in top of surface casing with 5 sacks of cement. Remainder of hole filled with low water loss mud. Location restored to original level.

C O P Y

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George L. Buckles Company
 Address P. O. Box 56
Monahans, Texas
 By Orig./s/ Robert M. Orr
 Title Chief Engineer