

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT (Other  
verse side)

REPLICATE\*  
Sections on re-

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

L.C. 068282-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT/AGREEMENT NAME

8. FARM OR LEASE NAME

Hanson Federal - Tr. 2

9. WELL NO.

12

10. FIELD AND FOOT, OR WILDCAT

Mason Delaware, North

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 25 - 26S - 31E

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Ernest A. Hanson

3. ADDRESS OF OPERATOR

P. O. Box 1515, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

330' FNL & 330' FEL

Sec. 25, T-26-S, R-31-E, N.M.P.M.

Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3169' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Hot Oil Well

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

As per request of Mr. Richard L. Stamets, N.M.O.C.C., Artesia, New Mexico,  
the following report of work is hereby submitted for your approval:

November 28, 1967 (1). Pulling unit pulled rods from well.

(2). Hot oil truck circulated hot oil down casing annulus  
and back to surface via 2-3/8" tubing for approximately  
2-1/2 hours.

(3). Pulling unit reran rods and new pump.

RECEIVED  
DEC 30 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Harry F. Schuman*

TITLE Exploration Manager

DATE 12-19-67

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

L.C. 20-1587  
R. L. BEAMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side