

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other in
verse side)REPLICATE
tions on re-Form approved.
Budget Bureau No. 42-R1424.

D. LEASE DESIGNATION AND SERIAL NO.

L.C. 068282-B

E. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hanson Federal - Tr. 2

9. WELL NO.

13

10. FIELD AND POOL, OR WILDCAT

Mason Delaware, North

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 25 - 26S - 31E

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Ernest A. Hanson

3. ADDRESS OF OPERATOR

P. O. Box 1515, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface330' FNL & 1650' FEL
Sec. 25, T-26-S, R-31-E, N.M.P.M.
Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3169' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Hot Oil Well

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As per request of Mr. Richard L. Stamets, N.M.O.C.C., Artesia, New Mexico, the following report of work is hereby submitted for your approval:

November 29, 1967 (1). Pulling unit pulled rods from well.

(2). Hot oil truck circulated hot oil down casing annulus and back to surface via 2-3/8" tubing for approximately 2-1/2 hours.

(3). Pulling unit reran rods and new pump.

RECEIVED
DEC 20 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry A. Schuman

TITLE

Exploration Manager

DATE 12-19-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
L.C. 20-352
R. L. BELLMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side