

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN PLICATE\*  
(Other instr. on re-  
verse side)Form approved. *Copy 37*  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

070869A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

None

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

White Federal NCT-1

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Mason, North Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 26, T-26-S, R-31-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐2. NAME OF OPERATOR  
TEXACO Inc.3. ADDRESS OF OPERATOR  
P. O. Drawer 728 - Hobbs, New Mexico4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface1830' from the South line and 330' from the East line of  
Sec. 26, T-26-S, R-31-E, Eddy County, New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3120' (GR)

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Subject well was completed in the Mason, North Delaware Field. Well was stimulated with a frac treatment in this zone as per USGS approval dated October 2, 1963.

The following work has been completed:

1. Pulled rods and pump.
2. Fractured down 2" tubing into casing perforations from 4112' to 4138' with 3000 gals lease crude, and 3000 pounds of sand at the rate of 4.7 BPM.
3. Recovered load.
4. On 24 hour Potential Test ending 11:00 A.M. December 17, 1963, well pumped 3 BO and 12 BW. Gravity 41.2°, GOR TSTM.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE

Assistant

District Superintendent

DATE

December 19, 1963

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
DEC 23 1963K. L. DEERMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side