

PETE MILLS

Oil & Gas Operator

706 Boyd
Midland, TX 79705

Phone
(915) 682-4596

August 30, 1995

RECEIVED

AUG 31 1995

OIL CON. DIV.
DIST. 2

Energy Minerals & Natural Resources Dept.
Oil Conservation Division
Artesia District Office
811 South First St.
Artesia, New Mexico 88210

ATTN: D. Ray Smith

RE: Russel 35 Fed.Well #2 A-35-26-31
August 28, 1995 Integrity Test

1. Unset packer, came out of hole, found hole in tubing 20 joints from service.
2. Picked up 1 Jt. tubing, ran new lock-set coated packer in hole.
3. 129 Jt. 2 3/8 plastic line tubing 3991.46
4. K.B. 11.00
5. Packer 4.00
6. Bottom of packer 4006.46
7. Set packer, pulled 14 points
8. Filled casing with packer fluid, bleed trapped air.
9. Pressured up back side to 340#
10. Put recorder on, held pressure for 15 minutes.



Pete Mills