



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **LC 068331**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 11, 19 63

Hanson-Federal

Well No. 1 is located 660 ft. from EN line and 660 ft. from EX line of sec. 20

SW/4 SW/4 Sec. 20 26 S 31 E 101N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcat Udy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12 1/4" hole 5:30 A.M. 2/9/63. Cemented 8 5/8" 28# casing at 328 feet with 125 sacks 4% gel and 50 sacks 2% calcium chloride. Plug down 4:15 P.M. 2/10/63. Cement circulated. WOC 24 hours and pressure tested casing with 1,000# for 30 minutes. Test O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Max M. Wilson

Address c/o Oil Reports & Gas Services

Box 763

Robbs, New Mexico

By A. L. Smith

Title Agent