

(SUBMIT IN TRIPLICATE)

Land Office

LC-068331

Lease No.

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 18, 1963

Hanson Federal

Well No. 1 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 20

SW/4 SW/4 Sec. 20

26 S

31 E

NTPM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Wildcat

Eddy

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned February 24 and February 25, 1963 as follows:

Total depth 5509, 8 5/8" at 328 feet left in hole. Spotted cement plugs 3000 to 5100 with 30 sacks, 3950 to 4230 with 50 sacks cement 2 1/2 HD-5 and 25 sacks sand, 3850 to 3950 with 30 sacks, 2300 to 2400 with 30 sacks, 1000 to 1100 with 30 sacks and 10 sacks in top of 8 5/8" casing with regulation marker. Rotary mud between all plugs.

Location is cleared and levelled and ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Max M. Wilson

Address c/o Oil Reports & Gas Services

Box 763

Hobbs, New Mexico

By

Title Agent