

N. M. O. C. G. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT 1. REPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 0522
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ *Drilling*

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
Box 68, Hobbs, N. M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL x 660' FEL, Sec. 28 (Unit P, SE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)
3502' R. D. B.

7. UNIT AGREEMENT NAME
POKER LAKE UNIT FEDERAL

8. FARM OR LEASE NAME

9. WELL NO.
36

10. FIELD AND POOL, OR WILDCAT
WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
28-24-31 NMPM

12. COUNTY OR PARISH
EDDY

13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 10/21/66, 9 5/8" OD 47-53.5" S-95 casing was set at 12,551' w/ 2300# Injurno Cement. After 740C 18 hours, tested casing w/ 4000 psi for 30 minutes. Just OK.

Reduced hole to 8 3/4" @ 12,551 and resumed drilling operations.

RECEIVED

RECEIVED
OCT 26 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE *Area Supt*

DATE *10-25-66*

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY.

TITLE

DATE

044-USGS-ART
1-NSO
1-SUSP
1-RRY
1-State Land-SF
1-INTOCC-SF
1-P. R. BASS
2-PAULEY PETRO CORP

APPROVED
OCT 28 1966
R. L. BEEKMAN
DISTRICT ENGINEER

*See Instructions on Reverse Side