

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other Instructi
verse side)TE
reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0522

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

POKER LAKE UNIT Federal

8. FARM OR LEASE NAME

9. WELL NO.

36

10. FIELD AND POOL, OR WILLIAM

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28-24-31 NMPM

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRY HOLE

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL * 660' FEL Sec 28 (Unit P, SE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3502' R. D. B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*Physical abandonment of hole made 3-14-68.
Cement plugs set and casing pulled as follows:100SX - 13,170 - 12710 (Perfs 12843 - 12961)
100SX - In and out of 7" casing stub @ 11470'
50 SX - In and out of 2 7/8" casing stub @ 7730'
100SX - 6100' - 6008'
100SX - 4560 - 4460
10SX - At Surface and erected P.A. marker.Subsequent report to be filed upon Final
Cleanup and restoration of ground to pitour.Note well assigned
to BLM 10-21-70RECEIVED
MAR 25 1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE 3-21-68

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL AND:

TITLE

DATE

0+4- USGS, ART
1- NSW
1- SOSD
1- W7
1- RLV
1- STATE LAND
1- NIMOL-57
1- PERRY BASS
1- DAULEY
1- SUPERIOR

*See Instructions on Reverse Side