

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI-CATE*
(Other instructions on re-verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME NONE	
2. NAME OF OPERATOR TEXACO Inc.		8. FARM OR LEASE NAME M. M. Stewart Federal	
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 660' from the North Line, and 660' from the East Line of Section 4, T-24-S, R-31-E, Eddy County, N. M.		10. FIELD AND POOL, OR WILDCAT Undesignated Delaware	
14. PERMIT NO. Regular		15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3415' (GR)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 4, T-24-S, R-31-E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input checked="" type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Total Depth - 566'
Spudded 9 5/8" Hole at 10:15 P. M. November 25, 1966

Ran 552' of 7 5/8" O. D. Casing, 24.00 LB, H-40, NEW, and cemented at 566' with 300 Sx. Class "C" cement. Plug at 535'. Cement Circulated. Job complete 6:30 A. M. November 25, 1966.

Tested 7 5/8" O. D. Casing for 30 minutes with 600 P. S. I. from 5:00 P. M. to 5:30 P. M. November 27, 1966. Tested O. K. Drilled cement plug and re-tested for 30 minutes with 600 P. S. I. from 7:00 P. M. to 7:30 P. M. November 27, 1966. Tested O. K. Job complete 7:30 P. M. November 27, 1966.

RECEIVED

NOV 30 1966

U. S. G. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett
(This space for Federal or State office use)

TITLE Assistant District

Superintendent

DATE November 28, 1966

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
NOV 29 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO