

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
WITH INSTRUCTIONS
ATTACHED

ATE

Name approved
Subject approved
State approved

NY-0502925A

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT A WELL OR NOT
2. NAME OF OPERATOR Black River Corporation	8. PATH OF WELL CASE
3. ADDRESS OF OPERATOR 620 Commercial Bank Tower, Midland, Texas 79701	38-Federal
4. LOCATION. Attach map or location clearly and in accordance with any State requirements. Sketch shown below: 1650' ENL & FEL of Section 5	9. WELL NO.
14. PERMIT NO. 30-315-20527	10. ELEVATIONS. From whether DE, TL, or (GL) 3858' GL - 3783 RKB
Approved 11/1/71	11. DATE & TIME Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT ON:
TEST WATER SHUT-OFF	WATER SHUT-OFF
FRAC TURE TREAT	FRAC TURE TREATMENT
SHUT IN OR ABANDON	SHUTTING OR ABANDONING
CHANGE WELL	CHANGE PLANS
17. A SUMMARY OF PROPOSED OR COMPLETED OPERATIONS (If only state of treatment details are given, treatment dates, including start and stop dates, are required. If well is directionally drilled, also subsurface locations of packers and other pertinent data for all work.)	

The subject well was plugged and abandoned on May 18th & 19th in the following manner: The tubing with packer was pulled from the well and the casing was shot off at 33 feet and pulled from the well. A 20 sack cement plug was spotted from 5990' - 6000' across the open perforations. A 20 sack plug was set from 4875' to 4875'. In and out of the 3-1/2" casing stub. A 30 sack plug was set from 3475' to 3375' in 7-7/8" casing and a 20 sack plug was set from 2015' to 2115'. A 30 sack plug was then set from 660' to 740', in and out of the 8-5/8" surface casing which was set at 660'. A 20" plug was set at the surface. The 8-5/8" casing was then capped with a steel plate welded onto it with an appropriate marker welded to the steel plate. Final location clean up is pending removal of tubular goods from location. The USGS will be notified when location is ready for final inspection.

18. I hereby certify that the foregoing is true and correct.

SIGNED: J. T. Barry Agent DATE: 7/26/72

(This space for Federal or State office use)

APPROVED BY: [Signature] DATE: 7/26/72

APPROVAL, IF ANY:

APPROVED

FEB - 1 1972

K. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side