

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0528035-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Midwest Oil Corporation

3. ADDRESS OF OPERATOR
1500 Wilco Building Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FNL & 1980' FWL

OCT 10 1973

7. UNIT AGREEMENT NAME

Cottonwood Spring Unit

8. FARM OR LEASE NAME

Cottonwood Spring Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

20-25S-26E

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

Gr. 3394'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) spud, csg

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-27-73 Spud 17 1/2" hole @ 4:45 PM.

9-29-73 Ran 14 jts (439') 13 3/8" 48# H-40 csg, set @ 419'. Cmt'd w/420 sx Class "C" w/2% D-33 14.8#/gal. Circ 30 sx to surf. WOC 18 hr. Tested BOP's to 1000 psi for 30 min, held OK.

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Richardson

TITLE Production Clerk

DATE 10-5-73

BH:ng 10-8-73

(This space for Federal or State office use)

DATE

TITLE

APPROVED
CONDITIONS OF APPROVAL, IF ANY:OCT 9 - 1973
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
OCT 9 1973
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO