Form 9-331 (May 1963) UNITED STATES

SUBMIT IN TRIPLICATE\*

DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side) **UniTED STATES** Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY NM 0457116 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (1) not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) RECEIVED 7. UNIT AGREEMENT NAME WELL X WELL NAME OF OPERATOR 8. FARM OR LEASE NAME NOV - J 1973 Midwest Oil Corporation
3. ADDRESS OF OPERATOR Federal "0" 9. WELL NO. 1500 Wilco Bldg. Midland, Texas LOCATION OF WELL (Report location clearly and in accordance with any State requirements. OF 10. FIELD AND POOL, OR WILDCAT At surface Wildcat 1980' FNL & 1980' FEL 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 11-26S-25E 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 12. COUNTY OR PARISH | 13. STATE Gr. 3643.06' N. Mex. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ARANDON\* SHOOTING OR ACIDIZING ABANDONMENT\* Х (Other) Spud REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* Change of Plans: Spud w/17 1/4" hole, rotary rig - drl to 200', change hole size to 7 7/8" & drl to 400'. If no lost circ, come out of hole & set 13 3/8", 48# csg @ 200' w/350 sx. encounter lost circ, set surf csg @ that depth. 10-25-73 Spud @ 3:30 PM, 17 1/4" hole 10-27-73 Drlg 119' anhy. Shut down for repairs on rotary table 10-29-73 Repairs comp, back to drlg. 10-31-73 Drlg 197' 1m, anhy 18. I hereby certify that the foregoing is true, and correct DATE 11-1-73 TITLE Production Clerk APPROVED BY DATE CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side