

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|  |  |  |  |
|--|--|--|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry   |  | 5. LEASE DESIGNATION AND SERIAL NO.<br>NM 0475504              |  |
| 2. NAME OF OPERATOR<br>Midwest Oil Corporation   |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                           |  |
| 3. ADDRESS OF OPERATOR<br>1500 Wilco Bldg. Midland, Texas  |  | 7. UNIT AGREEMENT NAME   |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2080' FNL & 1980' FWL |  | 8. FARM OR LEASE NAME<br>Federal "N"                           |  |
| 14. PERMIT NO.<br>30-015-21001   |  | 9. WELL NO.<br>1   |  |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)   |  | 10. FIELD AND POOL, OR WILDCAT<br>Wildcat                      |  |
|  |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>21-25S-26E |  |
|  |  | 12. COUNTY OR PARISH<br>Eddy                                   |  |
|  |  | 13. STATE<br>New Mexico  |  |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

|  |   |
|--|---|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETE <input type="checkbox"/>    |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input type="checkbox"/>             |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANS <input type="checkbox"/>         |
| (Other) <input type="checkbox"/>             |   |

SUBSEQUENT REPORT OF:

|  |  |
|--|--|
| WATER SHUT-OFF <input type="checkbox"/>        | REPAIRING WELL <input type="checkbox"/>          |
| FRACTURE TREATMENT <input type="checkbox"/>    | ALTERING CASING <input type="checkbox"/>         |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input checked="" type="checkbox"/> |
| (Other) <input type="checkbox"/>               |  |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Surf csg: 17 1/2" hole - 13 3/8" 45# csg @ 224'. Cmt w/300 sx Class "C" 2% CaCl

TD 2000'

12-10-73 P&A well by setting 100' plugs @ the following:

35 sx @ 1730-1830

35 sx @ 940-1040

65 sx @ 165-265

35 sx @ surface

Well was filled with mud laden fluid between plugs

RECEIVED

DEC 14 1973

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Bonnie Husband

TITLE Production Clerk

DATE 12-13-73

(This space for Federal or State office use)

BH:ng

APPROVED  
APR 24 1974  
R. L. BECKMAN  
ACTING DISTRICT ENGINEER

TITLE

DATE

\*See Instructions on Reverse Side

posted  
4-26-74