

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other Instructions on reverse side)Form Approved by GSA
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM0476685-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME HAY HOLLOW UNIT
2. NAME OF OPERATOR GREAT WESTERN DRILLING COMPANY ✓		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P. O. BOX 1659 MIDLAND, TEXAS 79701		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2080' FSL & 1980' FEL, Section 11, T-26-S, R-27-E		10. FIELD AND POOL, OR WILDCAT WILDCAT
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T26S, R27E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3214' GR		12. COUNTY OR PARISH EDDY
		13. STATE NEW MEXICO

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FILL OR ALTER CASING

WATER SHUT-OFF

SUBSEQUENT REPORT OF:

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

REPAIRING WELL

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ALTERING CASING

REPAIR WELL

CHANGE PLANS

(Other)

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED WORK TO BE DONE IN DETAIL. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is intentionally plugged, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 17 jts. (650.08') of 13-3/8" OD, 48#/ft. H-40E, ST&C Lone Star Csg. and set at 670'. Cemented with 650 sacks Class "C" + 2% CaCl. PD @ 6:45 AM 1-11-75.
Cement circulated - 100 sx excess. WOC 18 hrs. Tested csg. & BOP to 1000psi for 30 minutes - held. Top of cement inside csg. @ 631'.

RECEIVED
JAN 20 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

Assistant Chief Engineer

DATE 1-15-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side