

DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)  
GEOLOGICAL SURVEY

5. LEASE DESIGNATION AND SERIAL NO.

NM 0506-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Drilled and abandoned. **RECEIVED**

2. NAME OF OPERATOR

Perry R. Bass

SEP 27 1976

3. ADDRESS OF OPERATOR

Box 2760; Midland, Texas 79701

O. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

660' FSL, 660' FWL, Section -- Unit letter M

7. UNIT AGREEMENT NAME

Poker Lake Unit

8. FARM OR LEASE NAME

Poker Lake Unit

9. WELL NO.

43

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21, T24S, R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3497 Gr.

12. COUNTY OR PARISH

Eddy

13. STATE

New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TD 4481  
Drilled 7 7/8" hole to 4388'. Cut core #1, 4388-4420', cut and recovered 32'. Cut core #2, 4420-4480' cut 60'; recovered 56'. Ran logs. Shot 29 sidewall cores from 4399' to 4478'. Recovered 29 cores. Swung DP at 4174'; spotted 35 sx. Cl. H, 15.6 PPG cement from 4174' to 4074', across the base of salt. Pulled up to 2400' -- spotted 35 sx. Cl. H, 15.6 PPG cement from 2400' to 2300'. Pulled up to 649'; spotted 35 sx. Cl. H, 15.6 PPG cement from 649' to 549', across base of surface casing. Completed at 4:00 p.m. 1-4-76. Released rig at 8:00 p.m., 1-4-76. Surface marker set 1-13-76. Final clean up not yet made.

RECEIVED  
JAN 16 1976  
U.S. GEOLOGICAL SURVEY  
MIDLAND, TEXAS

18. I hereby certify that the foregoing is true and correct

SIGNED

*H. D. Murty, Jr.*

TITLE Division Production Clerk DATE January 16, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

Part 2  
ID 2  
3-19-76