

Form 9-331
Dec. 1973

JAN 15 1980

Form Approved.
Budget Bureau No. 42-R1424UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
O. C. D.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other2. NAME OF OPERATOR
Coquina Oil Corporation3. ADDRESS OF OPERATOR
P. O. Drawer 2960 Midland, TX 797024. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL; 1980' FWL of Sec. 12
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other)

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒5. LEASE
NM -- 80346. IF INDIAN, ALLOTTEE OR TRIBE NAME
--7. UNIT AGREEMENT NAME
--8. FARM OR LEASE NAME
El Paso Federal9. WELL NO.
#110. FIELD OR WILDCAT NAME *Cotton Draw*
~~Wildcat~~ -- Delaware11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA
12--24S--31E12. COUNTY OR PARISH | 13. STATE
Eddy | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
KB 3553'; GL 3540'(NOTE: Report results of multiple completions or zone
change on Form 9-330.)

RECEIVED

APR 27 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned beginning on 4/9/79. Plugs were set at the following depths.

Plug#	Type	Set @
1	CIBP	4500' w/35' cmt
2	50 SXS	3445'-3271' across csg stub
3	50 SXS	1945'-1771'
4	50 SXS	1100'- 926'
5	75 SXS	376 - 210'
6	15 SXS	@ surface

Cut off wellhead and welded on marker. Notice was given and plugs were witnessed by USGS personnel. P&A was completed on 4/14/79.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED James F. Buchanan, III TITLE Engineer Asst. DATE April 25, 1979

(This space for Federal or State office use)

APPROVED BY ALBERT B. STALL TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

ACTING DISTRICT ENGINEER

JAN 14 1980