

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

# SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ Core Test

2. NAME OF OPERATOR

Mobil Oil Corporation ✓

3. ADDRESS OF OPERATOR

9 Greenway Plaza, Suite 2700, Hous., TX 77046

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FSL & 1800' FEL of Sec. 15

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) Spud, set 10-3/4" csg.

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

DEC 2 1978

U.S. GEOLOGICAL SURVEY  
ARTESIA, OFFICE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 10:30 AM, 11/30/78. Drld. to 355'; ran 10 jts. 10-3/4" surface csg, set @ 353'. Cmt. with 325 x Class C + 2% CaCl<sub>2</sub>. Cmt. circulated. PD 5 PM, 11/30/78.

RECEIVED  
DEC 7 1978  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Virginia Howard TITLE Authorized Agent DATE 12/5/78

(This space for Federal or State office use)

ACTING DISTRICT ENGINEER

APPROVED BY Joe A. Lara TITLE \_\_\_\_\_ DATE DEC 11 1978

CONDITIONS OF APPROVAL, IF ANY: