Form 9-331 Dec. 1973	Form Approved. Copy D - Budget Bureau No. 42-R1424
UN J STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM-26103
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a diverent reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas well well well other MAR 6 1979	Federal K
2. NAME OF OPERATOR Amoco Production Company . D. C. C.	1 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	and. Morrow
 P.O. Drawer "A", Levelland, TX 79336 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28-25-27
AT SURFACE: 1980' FNL & 1980' FEL, Sec 28, AT TOP PROD. INTERVAL: (Unit G, SW ¹ / ₄ NE ¹ / ₄) AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Eddy NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3111.8 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF Image: Constraint of the second seco	(NOTE: Report results of multiple clarage change on FMMAR330.) U.S. GEULUGICAL SURVEY U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
Drilled to TD of 2000' (1/22/79) and set 10 3/4" 40.5# K-55 ST & C casing at 2000'. Cemented with 1100 sx Trinity Lite with 5% Gilsonite and .25#/sx Flocele and 8% CACL and 200 sx Class C and 2% CACL. Circulated 80 sx. Plugged down 3:30 a.m. 1/23/79. WOC 18 1/2 hrs. Tested casing with 1000# for 30 min. Tested 0.K. Reduced hole to 9 1/2" and resumed drilling.	
Drilled to TD of 11000' (2/18/79) and set 7 5/8" 33.7# & 39# S-95 LT & C casing at 11000'. Cemented with 2550 sx Trinity Lite and 300 sx Class H. Cement did not circulate. Plugged down 3:30 a.m. 2/19/79. Top of cement found at 1750' by temperature survey.	
Subsurface Safety Valve: Manu, and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED	isor February 27, 1979
APPROVED BY JUL A JALA TITLE	
0+4-USGS,A 1-Napco 1-Sabine Pro 1-Houston 1-Mesa Petroleum 1-Susp 1-El Paso Natural Gas	bate bare when a more and a more
1-SUSP 1-ET PASO NATURAL GAS 1-RWA *See instructions on Reverse Side	

;

T

.

•

.4

Ŧ

; ;

.

: