

N.M.O.C.D. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 02860

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐
WELL ☐ WELL ☒

2. NAME OF OPERATOR

PERRY R. BASS

3. ADDRESS OF OPERATOR

Box 2760, MIDLAND, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations, NEW MEXICO
See also space 17 below.)
At surface

1960' FNL 1990' FNL OF SECTION - UNIT LETTER

7. UNIT AGREEMENT NAME

POKER LAKE UNIT

8. FARM OR LEASE NAME

POKELAKE UNIT

9. WELL NO.

49

10. FIELD AND POOL, OR WILDCAT

WILDCAT MOVIE W

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 17, T24S, R30E

14. PERMIT NO. MAY 13 1981

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3248' GR 3270' KB

12. COUNTY OR PARISH

EDDY

13. STATE

N. MEX.

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

DRILLED 8 3/4" HOLE TO 11,522'. RAN 289 JTS 7" 23# & 26# N-80
AND S-95 CASING. SET @ 11,522'. CEMENTED W/975 SKS CLASS "H" PLUS
ADDITIVES. CALC. TOC @ 8500'. PLUG DOWN @ 4:00 PM, 2/16/81. WOC 48
HOURS. TESTED RAMS & CHOKER MANIFOLD TO 5000#, HYDRIL TO 7500# -
HELD OK. TESTED SHOE JOINT TO 750# - HELD OK. DRILLED 6 1/4" HOLE
TO 14,470'. RAN 78 JTS 5" FLUSH JOINT N-80 CASING W/ BOT HANGER
& FLOAT EQUIP. CEMENTED W/360 SKS CLASS "H". PLUG DOWN @ 6:20 AM,
4/4/81. HAD FULL RETURNS THROUGHOUT JOB. TOP OF LINER @ 11,182'.
TESTED CASING TO 4000# - HELD OK. RELEASED RLG @ 2:00 PM, MDST
4/6/81.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. D. Marty Jr.

TITLE

Sr. Prod. Clerk

DATE

May 6, 1981

(This space for Federal or State official use)

APPROVED BY

ROGER A. CHAPMAN

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 11 1981

U.S. GEOLOGICAL SURVEY
PO BOX 980, NEW MEXICO

*See Instructions on Reverse Side