

6-USGS-Roswell

1-CK-Foreman

1-File

8-WIOs

Form 9-331 1-PS-Engr.  
Dec. 1973Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

*C/SF*  
**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR  
Getty Oil Company /
3. ADDRESS OF OPERATOR  
P.O. Box 730, Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit Ltr. G, 1880' FNL & 1980' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

## SUBSEQUENT REPORT OF:

**RECEIVED**  
SEP 8 1981  
OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

5. LEASE  
NM-13413
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Salt Draw 11 Fed.
9. WELL NO.  
1
10. FIELD OR WILDCAT NAME  
Wildcat
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA  
Sec. 11, T25S, R28E
12. COUNTY OR PARISH  
Eddy
13. STATE
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
2425.4 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8/27/81 Drilled 26" hole to 437'. Ran 11 jts. (414') of 20" OD, 94#, K-55, 8rd casing and set @ 437'. Halliburton cemented w/1500 sxs. of class "C" cement w/2% CaCl & 1/4# flocele. Displaced to 95'. Total cement - 1800 sxs. Circulated 300 sxs. cement.

8/28/81 Waited on cement 21 hours. Pressured up on casing to 1200# for 30 minutes. OK.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED ROGER A. CHAPMAN TITLE Area Superintendent DATE 9/2/81

Dale R. Crockett (This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

SEP 8 1981  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO