0+5 - USGS-Roswell l - CK-Foreman 1 - File 8 - WIO's NM OIL CONS. COMMISSION 1 - PS-Engr. Form 9~331 Form Approved. Drawer DD Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATE Artesia, NM 88210 5. LEASE DEPARTMENT OF THE INTERIOR RECEIVED NM-13413 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME C/SF SEP 2 2 1981 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) O. C. D. 8. FARM OR LEASE NAME Salt Draw "11" Fed & FSIA OFFICE 1. oil well X well other 9. WELL NO. 2. NAME OF OPERATOR Getty Oil Company 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR Wildcat 清学学习企业人 P. O. Box 730, Hobbs, NM 88240 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 Sec. 11, T25S, R28E AT SURFACE: Unit ltr. G, 1880' FNL & 1980' FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: Eddy NM AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 2454.4 REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: 10**qs**1 TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL Report results of multiple completion or zone PULL OR ALTER CASING алge on Form 9-330.) MULTIPLE COMPLETE instructions CHANGE ZONES OIL & GAS ABANDON* U.S. GEOLOGICAL SURVEY (other) ROSWELL, NEW MEXICO 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Drilled 17 1/2" hole to 2620'. Ran 35 jts. 13 3 8 561 K-555 R-3 9/6/81 ST&C and 29 jts. 13 3/8" 48# H-40, R-3, ST&C and set @ 2604. Halliburton cemented w/3300 sxs Lite w/15% salt, 1/4#/sk. flocele and 5#/sk. Gilsonite. Tailed in w/200 sxs. class "C" cement w/1/4#/sk. Total cement - 3500 sxs. Circulated 600 sxs. cement. 9/8/81 Waited on cement for 18 hours. Pressured up on casing to 1000#. 36 and of b remant records <u>0</u> 5000 Subsurface Safety Valve: Manu. and Type _ 🖺 Set @ Ft. 18. I hereby certify that the foregoing is true and correct 8 9/10/81 TITLE Area Superintendent DATE Da ACCEPTED FOR SECOND ROGER A. CHAPMAN This space for Federal or State office use) $\pi \leq$ Vu. $\gtrsim 5$ APPROVED BY DATE CONDITIONS OF ASTERDIAL, OF 1981 position of the context of the conte 1 10 91s: აისისისიან სიმისის სიმისის U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO *See Instructions on Reverse Side