

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION

Drawer DD
Artesia, NM

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug bottom of a well or to plug a reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR

Sundance Oil Company

3. ADDRESS OF OPERATOR

1675 Larimer Street, Suite 800, Denver, CO 80202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2180' FNL and 1780' FEL

AT TOP PROD. INTERVAL: As above.

AT TOTAL DEPTH: As above.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☒

ABANDON* ☐

(other) ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is our intent to plug and abandon the Morrow Formation perforations and recompleate the well in the Brushy Canyon Sand as indicated on the attached procedure.

No additional surface will be disturbed.

RECEIVED
DEC 6 1982

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

D. H. Maroncelli

TITLE Drilling Manager

DATE

December 2, 1982

APPROVED BY
CONDITIONS OF

APPROVED
(ORIG. SGD.) DAVID R. GLASS

APPROVAL, IF ANY:

DEC 8 1982

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO