

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instruction
reverse side)Form approved.
Budget Bureau No. 42-R1424.

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		NM OIL CONS. COMMISSION		5. LEASE DESIGNATION AND SERIAL NO.
2. NAME OF OPERATOR		Drawer DD		NM 13989
3. ADDRESS OF OPERATOR		Artesia, NM 88210		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
600 Energy Square, 505 N. Big Spring, Midland, Texas 79701		RECEIVED		---
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		660' FNL & 990' FEL, Sec. 26, T-25-S, R-27-E		7. UNIT AGREEMENT NAME
OCT 5 1982		O. C. D.		---
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) ARTESIA, OFFICE		8. FARM OR LEASE NAME
		3075' GR, 3087' RKB		Amoco Federal
				9. WELL NO.
				1
				10. FIELD AND POOL, OR WILDCAT
				Wildcat
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
				Sec. 26, T-25-S, R-27-E
				12. COUNTY OR PARISH
				Eddy
				13. STATE
				New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

Install pumping equipment

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-3-82 thru 3-5-82

1. Pulled out RTBP from 6375'.
2. 2-3/8" tubing @ 6610'.
3. Ran 2" x 1 1/4" x 18' insert pump & rods.
4. Set 228 pumping unit.
5. Start pump testing Bone Springs perms 6064' to 6743'.

3-6-82 thru 4-26-82

Pumped 0 BO + 759 BW + trace of gas.

RECEIVED
SEP 13 1982OIL & GAS
MINERALS REVENUE SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct


SIGNED D. M. Johnson TITLE Prod. & Drlg. ManagerDATE 9-8-82

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side