UN. .D STATES

DEPARTMENT OF THE INTERIORD AWAR DD

NM 0525452-A

GEOLOGICAL SURVEY Artesia, NM	8831 ONDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other Storage	Washington Ranch Storage Project 9. WELL NO. WI Federal #8 10. FIELD OR WILDCAT NAME Washington Ranch 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3, T-26-S, R-24-E 12. COUNTY OR PARISH Eddy NM 14. API NO.
 2. NAME OF OPERATOR El Paso Natural Gas Co. 3. ADDRESS OF OPERATOR 1800 Wilco Bldg; Midland, Texas 79701 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 412' FWL & 2090' FNL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	NA 15. ELEVATIONS (SHOW DF, KDB, AND WD) GR 3757 *
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9 –330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinent	lirectionally drilled, give subsurface locations and
On 11/2/81 spudded 12 1/4" hole @ 9 AM, Young Drilled to 795', ran 9 5/8", 32.3#, H-40 cas w/500 sx Class "C" cement. Circulated 50 sx 2 PM, 11/4/81. WOC 18 1/2 hrs and tested cas test OK. Reduced hole to 8 3/4" and resumed	ing and set @ 795'. Cemented to surface. Job complete @ sing 800# for 30 minutes,

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct TITLE Suprv. Prod. Svc. DATE 11/18/81 SIGNED 1 1981 (This space for Federal or State office use) APPROVED BY CONDITIONS OF