Survey @ 10,910'=2°. Survey @ 11,240'= No good. 10- 2-82 10- 3-82 Coring. 10- 4-82 Coring. 10-5-82 Corina. 10-6-82 Drilling to 11,365'. Drilling to 11,420'. 10- 7-82 Drilling to 11,436'. 10- 8-82

Form 9-331

Dec. 1973

oil

well

below.)

AT SURFACE:

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

(other) Weekly Drilling

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON\*

**GEOLOGICAL** 

other

gas

well

Subsurface Safe	ety Valve: Manu. and Type Ft
18. I hereby ce	rtify that the foregoing is true and correct
SIGNED	ACCEPTED FOR THE Prod. Supt. DATE 10-11-82
APPROVED BY . CONDITIONS OF	(ORIG. 1900) DAVIO R. CHASS DATE  APPROVAD (TAILY 4 1982)
	U.S. GEOLOGICAL SURVEY  ROSWELL, NEW MEXICO en Instructions on Reverse Side