		NM OIL CONS. Drawer DD	COMMISSION	C158
	•		0007.6	- (
Form 9-331 (May 1963)	UNITED STAT	ES sur	88210 MIT IN TRIPLICATE:	Form approved.
, , , , , , , , , , , , , , , , , , , ,	DEPARTMENT OF THE	INTERIOR COL	er instructions on re-	Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SU			
CLU				6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	NDRY NOTICES AND RE			A THE NAME
, (Do not use thi	Is form for proposals to drill or to deep Use "APPLICATION FOR PERMIT-	-" for sugh proposits.)	illerent reservoir.	
1.		\$\q (	* 3	7. UNIT AGREEMENT NAME
MET WETT	OTHER			
2. NAME OF OPERATOR		R. W.	○ 158 <b>2</b>	S. FARM OR LEASE NAME
Gulf Oil	Corporation /		A CONTRACTOR OF THE STATE OF TH	Booth "BP" Fed
3. ADDRESS OF OPERAT	on	CH	& GAS	9. WELL NO.
PO. Bo:	x 670, Hobbs, NM 88240	O MINERALS.	MEAT. SERVICE	1
4. LOCATION OF WELL See also space 17 be	(Report location clearly and in accordar	nce with any 1030 111	NEW MEXICO	10. FIELU AND POPL OR WILDGAT
At surface			ut.a	Williast
990'	FNL & 660' FEL	NOV 1 0		11. SEC. T. R. M. OR REE. AND
		ROA I W	1302	BURYEY OR AREA
		Ci C	n	Sec 23-T26S-R29E
14. PERMIT SO.	15. ELEVATIONS (Sho	ow whether DF, RT, GR, cic.		12. COUNTY OR PARISU 13. STATE
		957' GL	/rr:ec	Eddy NM
16.	Check Appropriate Box To	Indicate Nature of	Notice Report of C	
NOTICE OF INTENTION TO				ENT REPORT OF:
TEST WATER SHUT	-OFF PULL OR ALTER CASING	, [ ] ,	TER SHUT-OFF	] · ·
FRACTURE TREAT	MULTIPLE COMPLETE	<del></del>	CTURE TREATMENT	REPAIRING WELL
RHOOT OR ACIDIZE	ABANDON*		OOTING OR ACIDIZING	ALTERING CASING
REPAIR WELL	CHANGE PLANS	[——]	ther) Casing	AUANDONMENT*
(Other)			(NOTE: Report results	of multiple completion on Well
17. DESCRIBE PROPOSED	OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, a	Completion of Recomple	etion Report and Log form.)
proposed work, nent to this work.	If well is directionally drilled, give sul	bsurface locations and n	seasured and true vertica	including estimated date of starting any I depths for all markers and zones perti-
				- · · · · · · · · · · · · · · · · · · ·
		·		
Cactus spu	dded 14-3/4" hole at 10:	:00 P.M., 10-2	2-82. TD 325'	at 12:30 A.M.,
10-24-82. RU & ran 8 joints and 1 cut joint 10-3/4" 40.5# K-55 ST&C. set at				
333'. Cement with 275 sacks Class "C" CaCl <sub>2</sub> & * celloflake + 150 sacks Class				
"C" CaCl <sub>2</sub> -did not circulate 1" annulus and cemented with 50 sacks Class "C"				
with $CaCl_2$ -did not circulate. Cement with 70 sacks $Class$ "C" with $CaCl_2$ .				
Circulate cement to surface. Test casing 1000#, ok. WOC 18 hours. Drill cement.				
Drilling fo	ormation 11:45 A.M., 10	-25-82.	,	
<u> </u>		-		•

8. I hereby certify that the torgolog is the and correct
SIGNED

(This space for Relera CCEPTED FOR RECORD

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

NOV 9 1982

U.S. GELLOGICAL SURVEYSee Instructions on Reverse Side