

C/SF

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
2. NAME OF OPERATOR
Santa Fe Exploration Company (505-623-2733)
3. ADDRESS OF OPERATOR
Box 1136/Roswell, NM 88201
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310' FSL & 990' FEL
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>

(other) Subsequent Report of 30 day suspension of operations

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/4/83 Moved equipment off location. Waiting on rig of larger capacity.
2/3/83 Moved in cable drilling rig. Rigged up. Prepare to remove 40' of 14" conductor pipe. Cut holes in pipe & jarred, could not pull. Rigged up and drilled 6 feet beside conductor pipe with 8" bit, SDON.
2/4/83 Drilled 22' beside conductor pipe with 8" bit. Shut down for weekend.
2/7/83 Drilled to TD of conductor pipe with 8" bit. Attempted to pull. Could not. Prep to drill to TD of conductor pipe on opposite side to attempt to remove. SDON.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jackie Minkler TITLE Agent DATE February 8, 1983

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS
CONDITIONS OF APPROVAL FEB 11 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

5. LEASE
NM-15302
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME Newyear Federal FEB 15 1983
9. WELL NO. 1 O. C. D.
10. FIELD OR WILDCAT NAME ARTESIA, OFFICE Wildcat
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 3-25S-29E
12. COUNTY OR PARISH Eddy 13. STATE NM
14. API NO. 30-015-24389
15. ELEVATIONS (SHOW DF, KDB, AND WD) 2993' G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
FEB 10 1983

MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO