STATE OF NEW MEXICO. ENERGY AND MINERALS DEPARTMENT		. •		
	CONSERVATION DIV		Form C-103	
DISTRIBUTION SANTA FE SAT	TA FE, NEW MEXICO 8	1	Revised 10-1-78	
FILE VV	SEP 3 0 1		Sa. Indicate Type of Lease	
LAND OFFICE	O. C. E			
OPERATOR V	ARTESIA, OF	1	5. State ()11 & Gas Lease No. LG 1177	
SUNDRY NOTICES AND	REPORTS ON WELLS			
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR T USE "APPLICATION FOR PERMIT IF	D DEEPEN OR PLUG BACK TO A DIFFERE ORM C-1011 FCR SUCH PROPOSALS.)	INT RESERVOIR.	7. Unit Agreement Name	
01L CAB			8. Farm or Lease Name	
Ray H. Haskins 30-01	5-24474		Getty State	
Address of Cycerator 9. Well No. First City Center One, Suite 1195, Midland, Texas 79701 1				
4. Location of Well	195, Miuranu, reza	5 19101	10. Field and Pool, or Wildcat	
UNIT LETTER I 1880 FEET PROP	THE SOUTH LINE AND 6	60 FEET FROM	Wildcat Burely Anyon	
THE East LINE SECTION 21	OWNSHIP 26 South RANGE 2	8 East NMPM.		
	tion (Show whether DF, RT, GR, etc)	12. County	
	974.4 Gr.		Eddy <u>Alllllll</u>	
Check Appropriate Box NOTICE OF INTENTION TO:	To Indicate Nature of Not		REPORT OF:	
PERFORM REMEDIAL WORK	AND ABANDON REMEDIAL WORK		ALTERING CASING	
TEMPORANILY ABANDON	COMMENCE DRIL	거	PLUG AND ABANDONMENT	
PULL OR ALTER CABING CHAI	IGE PLANS CASING TEST AN			
оти с я				
17. Describe Proposed or Completed Operations (Clearly sto	te all pertinent details, and give pe	rtinent dates, including	estimated date of starting any proposed	
work) see RULE 1103. Reason for Drilling Well	was spudded April	29. 1983. w	with a cable tool	
Reason for Drilling Well was spudded April 29, 1983, with a cable tool rig to set surface pipe, and to drill until a rotary rig could be moved in to drill a 6000' Brushy Canyon wildcat test.				
Posson to Plug and Abandon	- Well was drille	d to a TD of	94! when the	
Reason to Plug and Abandon Well was drilled to a TD of 94' when the decision was made not to drill a 6000' Brushy Canyon wildcat test as originally planned.				
Plugged and Abandoned C	n June 21, 1983, t	he well was	plugged and abandoned	
	by filling in the			
marker at the surface.				
			n	
			+D 33	
			0 7 75 3	
			10311- p+n	
			· · · · · · · · · · · · · · · · · · ·	
18. I hereby certify that the information above is true and co	mplete to the best of my knowledge	and belief.		
SIGNED Killy A. Hestin	Operator		DATE 9/29/83	
Durill Moore	the buolow	ist	DATE 1/17/86	
CONDITIONS OF APPROVAL, IF ANYI				

P. 0.	BRANER DD M MEXICO - Right BD
RAY HASKINS 1 st City Center 1, Stei 1195. MIDLAND, TX: 79781	DATE 3 - 84 RECEIVED BY JAN 051984 O. C. D. ARTESIA, OFFICE
Gentleman:	

Re: Plugging Reports

Form C-103, Report of Plugging for your <u>GETTY ST. #1 I - 21-26</u>23 Lease Well # Unit S-I-R

cannot be approved until a Division representative has made an inspection of the location and found it to be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.

- $(\mathcal{X}, 1, All pits have been filled and leveled.$
- ($\cancel{}$ 2. Rat hole and cellar have been filled and leveled.
- (') 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, towiship and range numbers which have been permanently stenciled or weided on the marker.
- () 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- (\checkmark) 5. The dead men and tie downs have been cut and removed.
- (1) 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk and equipment.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by filling in the black form below and returning this letter to us so that our represent-

OIL CONSERVATION DIVISION

Lang with

FILL IN BELOW AND RETURN

I certify	that the above work has been done	and the Getty of.
	$\overline{1-21-26-20}$ is ready for your	inspection and approval.
Well No	Unit S-T-R	$() \mathcal{A} \mathcal{A} \mathcal{A}$
norr ,o.		A all A, Necture
		Coerator 1/1/
		Cierator N. HASICINS
		Cperator