Form 9-331 NM_ OIL CONS. COMM	ISSION Form Approve	d ClSF	
UNITED STATES Artesia, NM 8821	0 Budget Bureau 5. LEASE	No. 42-R1424	
DEPARTMENT OF THE INTERIOR	US NM TT3997-	NM-13997	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRI	BENAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	RECEIVED BY	
1. oil gas well well other	Brushy Federa	MAY 1 1 1984	
2. NAME OF OPERATOR	9. WELL NO.]	O. C. D.	
El Paso Exploration Company 7	10. FIELD OR WILDCAT NAME ARTESIA, OFFICE Brushy Draw - Delawale		
1800 Wilco Building, Midland, TX 79701	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1700	AREA Sec. 35, T26S, R29E		
AT SURFACE: 330' FNL & 1750' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy New Mexico		
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 2862 GR		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF			
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone ?)		
PULL OR ALTER CASING	change on Form 9–330.)		
	a Jaco Maria		
ABANDON* (other) Drilling & Completion and Operator Name Change (10 ml C) (10 ml)			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d	e all pertinent details, and give period	ertinent dates, locations and	
measured and true vertical depths for all markers and zones pertinent to this work.)* Spudded 17 1/2" hole on 12/16/83 at 3:30 p.m., Willbros Rig #6. Drilled to 375'			
and ran 13 3/8", 48.0#, H-40 casing set at 32	d ran 13 3/8", 48.0#, H-40 casing set at 320'. Cmt. w/360 sxs. Cl. "C" cmt. and		
circ. 70 sxs. to surface. WOC 13 1/2 hrs. & tested csg. 500 psi., test ok. Re- duced hole to 12 1/4" and drilled to 2915' and ran 9 5/8", 36#, K-55 casing set at			
2914'. Cmt. w/700 sxs. Halco lite and 300 sxs. Cl. "C" cmt. RU 1" tubing and cmt.			
w/100 sxs. Cl. "C" and circ. cmt. to surface. WOC 12 1/2 hrs. and testing casing			
to 1500 psi, test ok. Reduced hole to 7 7/8" and drilled to 6000' and ran 4 1/2", 10.5#, K-55 csg. set at 5991' cemented w/500 sxs. 50-50 poz, bumped plug, floats			
held, good circulation. WOC 27 hrs. and tested casing 2500 psi, test ok. TOC at			
3980'. Released rig at 10:00 am 12/31/83. Waiting on completion on 1/9/84 RU DA & S pulling unit and TIH w/27/8" tbg. and drilled cmt. to 4257. POOH, RU, Mc-			
Cullough and perf. 4 SPF at 3800' to squeeze. Set pkr. at 3570' and cmt. w/400 sxs.			
50-50 poz, good circulation, job complete 10:			
remainder of description) Subsurface Safety Valve: Manu. and Type	Set @	Ft.	
18. I hereby certify that the foregoine is true and correct			
SIGNED HarAY LEP Mot chal RECOND _{TITLE} Area Drlg. En		1984	
(This space for Federal or State off			
APPROVED BY 9 1984 TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE		
1 01 0			
(alstad NEW MEXICO *See Instructions on Reverse :	Side		
	POST DETEN		

.

Released RTTS pkr. and POOH. Drilled out cmt. and tested casing to 2500 psi, test ok. Top of cement at 2398'. RU McCullough and perforated 1 SPF 4984 -5039. SION. On 1/14/84 TIH w/RTTS pkr. on 2 7/8" tbg., set pkr. at 4923. RU Howco & acidized w/2500 gals. MOD-101 acid. Balled off. max. press. 3500 psi. Load 90 bbls., bled off, swabbed dry, rec. est. 45 bbls. Well SI. RU Howco and fraced w/24,000 gals. 75% N2 Foam and 22,000# 20-40 sand plus 12,000# 10-20 sand. Job complete 11:20 a.m. 1/16/84. Well Shut-in on 1/20/84, TIH w/2 3/8" tbg. set at 5092'. Shut well in - WO potential test.