NM OIL CONS COMMISSION CIST Artesia, NM 88210

Form 3160-5 (June 1990)

12.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SHADDY MOTICES AND DEPORTS ON WELLS

FORM APPROVED Budget Bureau No. 1004~0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

NMNM 16814

Do not use this fo	6. If Indian, Allottee or Tribe Name		
~	su	BMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Type of Well Oil Well Gas Well	Other	SEP 16.94	8. Well Name and No.
. Name of Operator			Rodina Rodoral No. 2

Tide West Oil Company 9. API Well No. 3. Address and Telephone No. (918)30 01525579 Tulsa, Ok. 6666 S. Sheridan Rd., Suite 250, 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Brushy Draw - Delaware 330' FNL and 330' FWL 11. County or Parish, State NWNW Sec. 18 - 26S - 30E Eddy Co., New Mexico

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Request for TA Status → Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was MIT tested and witnessed on 11-7-91. The well is being evaluated for reactivation after 1-1-95, including possible clean out and re-stimulation of the current perforations @ 3411' - 3420' and 5411' - 5500'.

Estimated cost to clean out and treat \$20,000 \$50,000 Estimated cost to re-equip \$70,000

Tide West is requesting continued "Temporarily Abandoned" status until the well is reactivated. Work is anticipated by 2-1-95.

A new casing integrity test will be conducted by 9-15-94.

				•
14 I hereby certify that the foregoing is use and correct Signed	Title _	Operations Manager	Date _	8-16-94
(This space for Federal or State office use) (ORIG. SGD.) JOE G. LARA Approved by Conditions of approval, if any: Sac attached.	Title	PETROLEUM ENGINEER	Date _	9/14/44

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.