

12. Other Information:

- A. Topography: location is situated on a relatively flat dune basin.
- B. Vegetation: Yucca, mesquite, three-awn, black gramma.
- C. Surface is used for grazing cattle.
- D. An archeological survey on new access road and location conducted by Archaeological Survey Consultants, January, 3, 1991. No cultural sites present.

13. Operator's Representative:

John Tittl
Fortson Oil Company
3000 Texas American Bank Building
Fort Worth, Texas 76102
(817)335-5641

Certification:

I hereby certify that I, or persons under my direct supervision have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are to the best of my knowledge, true and correct; and that the work associated with the operations herein will be performed by FORTSON OIL COMPANY and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved. This statement is subject to the provisions of 18 U.S.C. 1001 for the filing of a false statement.

1/08/91
Date

Terry W. Franklin
Terry W. Franklin-
Agent