

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	7. If Unit or CA, Agreement Designation
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	8. Well Name and No. Corral Federal Unit #1
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	9. API Well No. 30-015-27522
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FEL of Section 33-T25S-R29E	10. Field and Pool, or Exploratory Area Wildcat Delaware
	11. County or Parish, State Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other Spud, surface casing & cement
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 26" hole at 5:25 PM 8-16-93. Drilled to 40' and set 40' of 20" conductor pipe. Cemented to surface. NOTE: Notified BLM in Carlsbad. Resumed drilling a 17-1/2" hole with rotary tools at 9:30 AM 8-19-93.

TD 466'. Ran 11 joints of 13-3/8" 54.5# J-55 (471.68') of casing set at 466'. 1-Texas Pattern notched guide shoe set at 466'. Insert float set at 418.29'. Cemented with 350 sacks Pacesetter Lite, 10#/sack gilsonite, 1/2#/sack celloseal and 3% CaCl2 (yield 2.01, weight 12.7). Tailed in with 200 sacks Class "C" 3% CaCl2 (yield 1.32, weight 14.8). PD 6:30 PM 8-19-93. Bumped plug to 700 psi, float held okay. Circulated 150 sacks. WOC. NOTE: Notified BLM. Drilled out at 12:30 PM 8-20-93. WOC 18 hours. Nippled up and tested to 1000# for 30 minutes, OK. Reduced hole to 12-1/4". Resumed drilling.

ACCEPTED FOR RECORD

J. Lee
OCT 12 1993

CARLSBAD, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed *Rusty Klein* Title Production Supervisor

Date Sept. 16, 1993

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____ Date _____