

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Bettis, Boyle & Stovall

3. Address and Telephone No.

P. O. Box 1240, Graham, TX 76450

817-549-0780

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FSL & 2310' FEL (NW/4 SE/4) SEC. 9, T24S, R31E

NM OIL CONS COMMISSION

Drawer DD

Budget Bureau No. 1004-0135

Artesia, NM

Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-29234

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Lotos Federal #4

9. API Well No.

30-015-27593

10. Field and Pool, or Exploratory Area

Delaware Wildcat

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other drilling

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11/18/93 - 6094' TD, made 869' last 24 hrs. Present operation is drilling. Formation is Lime/Sand. Survey @ 5588' - 3/4°.
11/19/93 - 6681' TD, made 587' last 24 hrs. Present operation is drilling. Formation is shale. Surveys @ 6094' - 1/4°; 6605' - 3/4°.
11/20/93 - 7264' TD, made 583' last 24 hrs. Present operation is drilling. Formation is Sand/shale. Survey @ 7100' - 1-1/2°.
11/21/93 - 7550' TD, made 286' last 24 hrs. Present operation is drilling. Formation is Sand/Shale. Cracked drill collar caused slow drilling and SD time f/ tripping.
11/22/93 - 8127' TD, made 577' last 24 hrs. Present operation is drilling, mudding up. Formation is Sand/Shale. Surveys @ 7589' - 1-1/2°; 8096' - 3/4°.
11/23/93 - 8251' TD, made 124' last 24 hrs. Present operation is logging. Formation is Sand/Shale. Halliburton Logging Serv. running DIL, LL, GR, DSN, SDL to TD of 8251'.

ACCEPTED FOR RECORD

(ORIG. SGD.) DAVID R. GLASS
1993

CARLSBAD, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed

Tim Hagen

Title

Regulatory Analyst

Date

11/23/93

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date