

(November 1984)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN THIS
DRAWER DD
Artesia, NM 88210

Expires August 31, 1985
LEASE DESIGNATION AND SERIAL

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR McKay Oil Corporation	8. FARM OR LEASE NAME Remmele Federal Com
4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.) At surface 1980' FWL & 660' FNL	9. WELL NO. 10
14. PERMIT NO.	10. FIELD AND POOL OR WILDCAT W. Pecos Slope-Abo
15. ELEVATIONS (Show whether DEPT. OR GR.) 4235' GR	11. SEC., T., R., M., OR B.L. AND SUBST OR AREA Sec. 26, T6S, R22E
	12. COUNTY OR PARISH Chaves
	13. STATE N.M.

RECEIVED BY
FEB 11 1987
O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACURE TREAT	MULTIPLE COMPLETION	FRACURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	OTHER:	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Proposed Access Road X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Operator proposes to construct an access road 14' wide by approximately 2350' in length as displayed on the enclosed topographic map. Proposed access road is on federal surface.


An archaeological survey was conducted on proposed access road by Archaeological Survey Consultants, under report #87-10.

JW9 Caliche pit for pad & access road
1/27/87

NW 1/4 SE 1/4
Sec 9, T6S, R22E

EXP INT
1-30-96


30-005-62384



18. I hereby certify that the foregoing is true and correct

SIGNED <u>Jerry W. Franklin</u>	TITLE <u>Landman</u>	DATE <u>1/27/87</u>
(This space for Federal or State office use)		
APPROVED BY <u>S/Phil Kirk</u>	TITLE <u>Area Manager</u>	DATE <u>FEB 6 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side



Map showing the location of the McKay Oil Corporation access road to the Remmele Fed. Comm. Well No. 10, Section 26, R22E, T6S, SW/4NE/4NE/4; SE/4NW/4NE/4; SW/4NW/4NE/4; SE/4NE/4NW/4. Chaves County, New Mexico. Open squares show locations of well pads; solid line shows location of access road. U.S.G.S. 7.5 minute series, MESA SW, NEW MEXICO, 1967. ASC Project: 87-10.