

11. OTHER INFORMATION:

- A. Topography: The topography is a gradual sloping the southwest in the vicinity of the access road and southeast in the vicinity of the drill pad. Regional slope is South toward the Arroyo del Macho which is approximately 1/2 mile from this location.
- B. Soil: Sandy loam with limestone outcropping.
- C. Flora and Fauna: The flora consists of typical desert vegetation, such as yucca, cactus and various grasses. Fauna consists of desert wild-life such as coyotes, rodents, snakes, deer and antelope.
- D. Ponds or Streams: Arroyo del Macho is about 1/2 mile south of the proposed location.
- E. Residences and other Structures: Boswell ranch house is approximately 2 3/4 mile southwest of this location.
- F. Archaeological, Historical and Other Cultural Sites: No artifacts are noted in the area of the pad or access road. An Archaeologist from Roswell, New Mexico (ASC) has checked the location and access road and furnishes a favorable recommendation.
- G. Land Use: Grazing
- H. Surface Ownership: Federal

12. OPERATOR'S REPRESENTATIVE:

Gary Richburg
Roswell, New Mexico
(505) 623-4735

13. CERTIFICATION:

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge true and correct; that the work