

of the access road and in the vicinity of the drill pad. Regional slope is Southwest toward the Arroyo del Macho which is approximately 3 miles from this location.

- B. Soil: Sandy loam with limestone outcropping.
- C. Flora and Fauna: The flora consists of typical desert vegetation, such as yucca, cactus and various grasses. Fauna consists of desert wildlife such as coyotes, rodents, snakes, deer and antelope.
- D. Ponds or Streams: Arroyo del Macho is about 3 miles southwest of this location.
- E. Residences and other Structures: J.Y. Ranch, Inc. house is approximately 2.3 miles west of this location.
- F. Archaeological, Historical and Other Cultural Sites: No artifacts are noted in the area of the pad or access road. An Archaeologist from Roswell, NM checked the location and has given a favorable recommendation.
- G. Land Use: Grazing
- H. Surface Ownership: Fee

12. OPERATOR'S REPRESENTATIVE:

Gary Richburg  
Roswell, New Mexico  
(505) 623-4735

13. CERTIFICATION:

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge true and correct; that the work