


Form 9-531a
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. **LC 063073-A**

Unit _____



DEC 29 1958

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 23, 19**58**

No. 10 Fokar Lake Unit A-4

Well No. _____ is located **1900** ft. from **[N]** line and **640** ft. from **[E]** line of sec. **14**

SW/4 of the NW/4 of sec. 14 **23E** **30E** **7**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox **Eddy** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **2340** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

140' - 14," 55# Casing, Surface String, Mudded in.
430' - 13 3/4," 40# Casing, Intermediate String, Mudded in.
1070' - 10 3/4," 30# Casing, Intermediate String, Mudded in.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Alamo Corporation, Agents for Richardson & Ross**

Address **1004 Lubbock Nat'l Bank Bldg.**
Lubbock, Texas

By **R. E. Jackson**
Title **Representative**