

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL  
(Other instructions  
verse side)

TE  
re

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-29234

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bran-Bettis Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat-Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 11, T24S-R31E, NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Branex Resources, Inc. (formerly Bran Oil Corporation)

3. ADDRESS OF OPERATOR

P.O. Box 2328, Roswell, New Mexico 88202-2328

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)  
At surface

660' FSL and 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3552' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

XX

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

SUBSEQUENT REPORT OF ABANDONMENT

April 27, 1987

Burleson Construction Co. of Loving N.M. ripped out all access roads to a minimum of 12" deep as well as the well pad. All pits were leveled and filled as per BLM specs. and all plastic pit liner material was removed. All ripped out area was reseeded with BLM spec. seed mixture #2. An earthen barricade was erected to prevent vehicular traffic using spoil material. The cellar was also filled and the location was clean up from all trash material and the trash was hauled off.

Approved by \_\_\_\_\_  
Title \_\_\_\_\_  
surface reclamation is completed.

RECEIVED  
SEP 23 9 50 AM '91  
CARRIZO  
AREA

18. I hereby certify that the foregoing is true and correct

SIGNED

*J. Andrew Brown*

TITLE President

DATE September 20, 1991

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 9/24/91

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side