

Deviation Report

| | | |
|--|---|---------------------------------------|
| Name of Company Burlington Resources Oil & Gas Company | Address P.O. Box 4289, Farmington, NM 87499 | |
| Lease Name and Number (API Number) ALLISON UNIT #131S (30-045-31861) | Location 1950 FNL -660 FWL | Sec. Twn. Rge. 24-032N-007W |
| Pool and Formation Basin Fruitland Coal | County SAN JUAN | State NEW MEXICO |

(OH)

| <u>Depth (ft)</u> | <u>Deviation (degrees)</u> |
|-------------------|----------------------------|
| 141 | 0.25 |
| 658 | 1.00 |
| 1,153 | 1.00 |
| 1,627 | 0.75 |
| 2,122 | 1.00 |
| 2,620 | 1.50 |
| 3,093 | 1.00 |

Air Hammer Used? YES / ☒ NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Sean Louigan

Subscribed and sworn to before me this 17th day of March, 2004.

Tamatha Wimsatt

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2004.

