

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
BURLINGTON
RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1220' FSL, 1850' FEL, Sec.33, T-31-N, R-11-W, NMPM, San Juan County

API # (assigned by OCD)
30-045-10064

5. Lease Number
Fee


6. State Oil&Gas Lease #

7. Lease Name/Unit Name
Oliver

8. Well No.
3

9. Pool Name or Wildcat
Aztec Pictured Cliffs

10. Elevation:



Type of Submission

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment

Type of Action

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other - Deepen

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut off
☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to restimulate the Pictured Cliffs formation in the subject well as follows:

Move in, rig up. Pull tubing. Deepen the well to approximately 200 feet below the top of the Pictured Cliffs formation. Run production casing. Cement casing to surface. Fracture stimulate the Pictured Cliffs formation. Return well to production.

SIGNATURE *Peggy Case* (KS4) Regulatory Supervisor March 6, 2003

no
(This space for State Use)

Approved by *[Signature]* Title DEPUTY OIL & GAS INSPECTOR, DIST. #1 Date MAR 10 2003