submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells	
	. Lease Number
	NMSF-078507
1. Type of Well	. If Indian, All. or
GAS	Tribe Name
	7. Unit Agreement Name
2. Name of Operator	-
BURLINGTON	
RESOURCES OIL & GAS COMPANY	
App App	3. Well Name & Number SAN JUAN 32-9 UNIT #3
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	API Well No.
	30-045-22899
4. Location of Well, Footage, Sec., T, R, M	0. Field and Pool
1815'FSL,1450'FEL, Sec.1, T31N, R10W, NMPM	BLANCO MESAVERDE
	11. County and State
S. E. California de la	San Juan Co, NM
10 OUTON ADDRODDIAME DOV MO TANDIONE NAMEDE OF NOMICE DEPORT	IND DAMA
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER Type of Submission Type of Action	IER DATA
Notice of Intent Abandonment Change of F	Plans
Recompletion New Constru	ıction
	Fracturing
Casing Repair Water Shut Final Abandonment Altering Casing Conversion	off to Injection
X Other	to injection
13. Describe Proposed or Completed Operations	
Burlington Resources did workover operations as per attached daily	
Bullington Resources did workover operations as per attached daily	summary.
	93
	3 4 m
ACCEPTED	FOR RECORD
APR 1	6 2004
FARMINGTON F BY	
BY	FUPFICE
7	
14. I hereby certify that the foregoing is true and correct.	7
Signed Hauces Bond Title Regulatory Specialist	Date 04/013/04
	fsb
(This space for Federal or State Office use) APPROVED BY Title Date	
CONDITION OF APPROVAL, if any:	

BURLINGTON RESOURCES

San Juan Division - Intranet Well Information System (DIMS)

Friday, April 2, 20

LogonBy	Date 🔻By	Well-	By AFE 👻	By Rig
Del-Aprila	roduction Notes-	-Accountability-	-Safety-	*
	įOtrier	API Units		

Export to Excel

Operations Detail Report for: SAN JUAN 32-9 UNIT #3A LOE WORK

Entire Well / All Events

Time Breakdown Summary

	ine dicardown Summary										
DAY	FROM	то	HRS	DEPTH (ft)	PHASE	CODE	S	OPERATION			
1	12/09/2003	16:00	1.00	1	PREWRK	MIMO	N	ROAD RIG AND CREW TO LOC.			
(LWK)	15:00					а					
1	12/09/2003	16:15	0.25		PREWRK	SAFE	Ν	SAFETY MEETING - RIGGING UP SAFELY,			
(LWK)	16:00					а		ALERT, DON'T GET IN A HURRY, GRASS			
		[[[[ĺ		HOPPER UNIT, WATCH THE WEIGHTS ON THE			
								PUMPING UNIT, SHUT OFF ALL POWER TO			
								ELECTRIC MOTOR ON PUMPING UNIT - 4 CREW,			
\sqsubseteq							=	RIG SUPERV., RIG MOVERS (2)			
	12/09/2003	17:15	1.00		MIRU		N	SPOT RIG, TRY AND RIG UP, TO CLOSE TO			
(LWK)	16:15					а		GRASSHOPPER, TUBING BOARD HIT UNIT, RIG			
								DOWN, MOVE RIG OVER A LITTLE, DON'T TILT			
								RIG ALL THE WAY OVER, SCOPE UP SOME SO TUBING BOARD WILL CLEAR, RIG UP RIG			
							_				
	12/09/2003	17:45	0.50	ļ	OBJECT		N	RIG DOWN HORSES HEAD, LD POLISH ROD, LD			
(LWK)	17:15					а		1 GUIDED ROD, PU POLISH ROD, SCREW IN			
\sqsubseteq			<u> </u>					STUFFING BOX,			
	12/09/2003	18:15	0.50		OBJECT	SHDN		WINTERIZE PUMP, PICKUP TOOLS, SECURE			
(LWK)	17:45					a	느	RIG, SDFN			
2	12/10/2003	07:00	1.00		PREWRK	MIMO	N	ROAD CREW TO LOC., WARM UP & SERVICE			
(LWK)	06:00					a	Ш	RIG			
2	12/10/2003	07:15	0.25		PREWRK	SAFE	N	SAFETY MEETING - LOCKOUT/TAGOUT,			
(LWK)	07:00		!			a	$\ \ $	ELECTRICAL SOURCE FOR PUMPING UNIT - 4			
								CREW, RIG SUPERV.			
2	12/10/2003	08:00	0.75		OBJECT	WAIT	M	WAIT ON HOT OILER, SOME PERSON CHANGED			
(LWK)						а		THE SIGN DIRECTION TO THE RIG,			
2	12/10/2003	09:00	1.00		OBJECT	ното	N	LOAD 30 BBLS WATER ON HOT OILER, HEAT UP			
(LWK)	08:00					a		WATER OFF LOC., PUMP WATER DOWN TUBING			
2	12/10/2003	10.30	1.50]	OBJECT		띡	RU FLOOR TO PULL RODS, HIGH WELLHEAD,			
(LWK)		10.50	1.50		OBJECT	a	'`	TOH POLISH ROD, 4' PR, 109 GUIDED .750, 128			
الحسيمة	اا ۵۶۰۰۵	11	l II	11	- 1	- u	i l	10011 OLIGH NOD, T FR, 103 GUIDED ./30, 120			

2 (LWK) 2 (LWK)	12/10/2003			OBJECT OBJECT	_ a		PLAIN .750 RODS, (SEEM TO BE STRETCHED OR EXTREMELY WORN WHEN LATCHING ONTO ELEVATORS, 1 SINKER BAR, PUMP (STACKED OUT) RD FLOOR, NDWH, NUBOP, RU FLOOR PU 1 JT. TBG, PULL DONUT, INSTALL STRIPPING RUBBER, TIH, HAVE ONE (1') FOOT
2 (LWK)	12/10/2003 12:00	15:00	3.00	OBJECT	TRIP a	N	OF RATHOLE???, HAD 44' OF RATHOLE IN MAY. TALLY OUT OF HOLE WITH TUBING. TWENTY STANDS TUBING OK, 20-25 STANDS, BADLLY BENT, 35 STANDS OUT TUBING SOFT. 10 BENT JOINTS, 25 SOFT JOINTS, SOME JOINTS CRIMPED ON OFF BREAK. BOTTOM 3 JOINTS BENT, TOH W/FOLLOWING: 192 - JTS. 2.375 EUE J-55 TUBING 1 - SEATING NIPPLE 1 - PERF. SUB (4') 1 - JT. 2.375 EUE J-55 4.7# TUBING 1 - BULL PLUG W/1" HOLE IN BOTTOM WAS LANDED @ 5993.20, SN @ 5955.90, IF PBTD OF 6021 IS CORRECT, THAT LEAVES 28' OF FILL
2 (LWK)	12/10/2003 15:00	16:00	1.00	OBJECT			WENT BACK UP AND DID A RECOUNT ON TUBING AND RODS
2 (LWK)	12/10/2003 16:00	16:30	0.50	OBJECT	SHDN a		CLOSE RAMS, LOCK, PU TOOLS, SECURE RIG, SDFN
3 (LWK)	12/11/2003 06:00	07:00	1.00	PREWRK	MIMO a	N	ROAD CREW TO LOC., WARM UP & SERV. RIG.
3 (LWK)	12/11/2003 07:00	07:15	0.25	PREWRK	SAFE a		SAFETY MEETING - 120# CASING, PRESSURES, ICE PLUGS, STAY CLEAR - 4 CREW, RIG SUPERV.
3 (LWK)	12/11/2003 07:15	12:00	4.75	ОВЈЕСТ	TRIP		PU BAILER, TIH, (FLAPPERS, 5 JOINTS TUBING, BAILER) CO 27' OF FILL, TAG ON FISH, SOLID, PULL UP WAIT 20 MINUTES, BAIL UNTIL TAGGING FISH, TOH WITH TUBING AND BAILER, JT #48 WAS ROD CUT, TUBING WAS SOFT, REPLACE 3 JOINTS BELOW AND 3 JOINTS ABOVE ROD CUT JOINT, LAYED DOWN TOTAL OF 20 JOINTS WHILE TRIPPING OUT OF THE HOLE, 2 JOINTS COMPLETELY FULL OF SAND BELOW TUBING BAILER.
3 (LWK)	12/11/2003 12:00	13:00	1.00	ОВЈЕСТ			REARRANGE TRAILER TO SEND TUBING TO TOWN ON HOTSHOT, 25 JTS JUNK 2.375 FROM 3A, 1 JT 2 1/16 FROM, DON'T HAVE ANY IDEA, MISC. PERF. SUBS
3 (LWK)	12/11/2003 13:00	15:30	2.50	OBJECT	TRIP		TIH W/25 BLUE BAND TUBING, 12 STANDS, LOAD TBG. W/WATER, PT TO 2500#, TIH, TOTAL OF 46 STANDS IN WELL, PT TO 2500#, STRING TESTED OK TO 2500#, ASSEMBLY BHA, TALLY 30 JOINTS OF TUBING, PU 25 JOINTS BLUE BAND OFF HOTSHOT, PUT OTHER 5 JOINTS ON THE RIG TRAILER., SEND 25 JOINTS JUNK TUBING TO BR YARD ON HOTSHOT TRUCK TIH W/FOLLOWING CONFIGURATION: 1

							- 2.375 EUE PURGE VALVE 1 - 2.375 EUE PUP JOINT (10') 1 - 3.061 COLLAR SIZE SEPARATOR 1 - 2.375 EUE PUP JOINT (3') 1 - 2.375 EUE PUP JOINT (12') 1 - 2.375 EUE SEATING NIPPLE 192 - JTS. 2.375 EUE J-55 4.7# EUE TUBING LAND @ 5998.63, SN @ 5966.86, FISH IN BOTTOM OF HOLE @ 6021 (FROM 1980?) NEW PBTD @ 6021, PRESSURE TESTED TUBING 2500# TOP TO BOTTOM, LONGSTRING OF 4 1/2", PERFS 5185-6025. KB 10'
3 (LWK)	12/11/2003 15:30	16:30	1.00		ОВЈЕСТ	FISH a	RU SINKER BAR, TIH WITH STANDING VALVE RETRIEVING TOOL, PULL STANDING VALVE AFTER WORKING IT.
3 (LWK)	12/11/2003 16:30	17:00	0.50		OBJECT	SHDN a	WINTERIZE PUMP, PUT TIW IN TUBING, PU TOOLS, SECURE AND LOCK RAMS, SDFN
(LWK)			1.00		PREWRK	MIMO a	ROAD CREW TO LOC., WARM UP & SERVICE RIG
4 (LWK)					PREWRK	SAFE a	SAFETY MEETING - DRESSING CORRECTLY, PREVENT BEING UNCOMFORTABLE FROM THE COLD, FROSTBITE, 4 RIG CREW, RIG SUPERV.
4 (LWK)	12/12/2003 07:15	08:45	1.50		OBJECT		LAND TUBING, SCREW IN LOCKDOWNS, RD FLOOR, NDBOP, NUWH, RU FLOOR.
4 (LWK)	12/12/2003 08:45		1.25		OBJECT		PU PUMP, TIH W/FOLLOWING: 1 - 2" X 1 1/4" X 10 X 14' INSERT PUMP, SCPID BBL, 4SM-003 PLUNGER, ALLOY/TC VALVES, 107" MAX STROKE, BR705, 3/4" PIN SIZE, SANDCHECK, SPIRAL ROD GUIDE, LIFT SUB 1 - 1.250 SINKER BAR 1750 PONY ROD (8') 128750 PLAIN SUCKER RODS 109750 GUIDED MOLDED SUCKER RODS 1 - 1.250 POLISH ROD W/10' LINER 1.500 1 - BIG STUFF STUFFING BOX
4 (LWK)	12/12/2003 10:00	11:00	1.00		OBJECT	PRES a	SEAT PUMP, LOAD TUBING W/WATER, PRESSURE TEST TO 1500#, OK, BO, LONGSTROKE TO 600, OK, GOOD PUMP ACTION, BLEED OFF (HAD TO JUMP PUMP)
4 (LWK)	12/12/2003 11:00	11:45	0.75		ОВЈЕСТ	RURD a	HARD TIME GETTING WEIGHT TO THE TOP TO RUHH RUHH, HO RODS, SET TAG
4 (LWK)	12/12/2003 11:45	13:30	1.75	e	OBJECT	RURD a	RIG DOWN RIG, CHANGE OUT KELLY HOSE THAT HAD A HOLE, RELEASE RIG @ 1330 HOURS, NOTIFY LEASE OPERATOR, MOVE TO SAN JUAN 32-9 # 26R MOVED ON LOCATION, HOT OILED, PULLED RODS, TAGGED, NO RATHOLE, TOH, TUBING BAD IN PLACES, TIH W/TUBING BAILER, CLEAN OUT 27' OF SAND, TOH LAYING DOWN BAD TUBING, JT 48 HAD A ROD CUT 1' LONG, CHANGED OUT 3 JOINTS ABOVE AND BELOW ROD CUT JOINT, CHANGED OUT 25 TOTAL JOINTS, TIH W/PRODUCTION STRING, PRESSURE TESTED TO 2500#, OK, LANDED TUBING, TIH W/NEW PUMP, PT TO 1500#, OK, GOOD PUMP ACTION, RIG DOWN RIG, CHANGE OUT KELLY HOSE THAT HAD A

	ı 1	1 1	ı ı 1				1 1	
								HOLE IN IT, RELEASE RIG, MOVE TO SJ 32-9 # 26R
5 (LWK)	03/19/2004 09:00	11:00	2.00		PREWRK	MIMO a	N	ROAD RIG AND CREW TO LOC FROM PAYNE 11
5 (LWK)					MIRU	RURD a		SPOT RIG, GRASSHOPPER, SET TO SIDE, HAVE TO RAISE DERRICK, LEAVE BACK SOME, SCOPE UP FAR ENOUGH TO HAVE TUBING BOARD MISS PUMPING UNIT, RIG UP.
5 (LWK)	03/19/2004 11:45	12:15	0.50		OBJECT	RURD a	N	RIG DOWN HORSES HEAD, UNSEAT PUMP, LAY DOWN POLISH ROD. RIG UP FLOOR
5 (LWK)	03/19/2004 12:15	13:30	1.25		OBJECT	TRIP a	N	TRIP OUT OF HOLE WITH RODS AND PUMP: POLISH ROD, 109 .750 GUIDED RODS, 128 .750 PLAIN SUCKER RODS, 8' PONY, 3 - 1.250 SINKER BARS, PUMP, PUMP WAS STACKED, ASPHALTINE IN BOTTOM,
5 (LWK)	03/19/2004 13:30	14:30	1.00		OBJECT	NUND a		RIG DOWN FLOOR, NIPPLE DOWN WELLHEAD, NIPPLE UP BLOW OUT PREVENTER, RIG UP FLOOR AND EQUIPMENT
5 (LWK)	03/19/2004 14:30	15:00	0.50		OBJECT	PULD a	N	PICKUP ONE JOINT, PULL TBG. HANGER, INSTALL STRIPPER RUBBER, TIH, TAG, STILL 22' OF RATHOLE, LAY DOWN JOINT OFF TRAILER
5 (LWK)	03/19/2004 15:00	16:30	1.50		ОВЈЕСТ	TRIP a	N	TOH W/96 JTS TUBING AND BHA, HAD 4 SOFT JOINTS, STARTED BLOWING OUT TUBING 15 STANDS FROM BOTTOM, PURE WATER, HAD APPROX 3' OF ASPHALTINE IN BOTTOM SUB,
5 (LWK)	03/19/2004 16:30	17:00	0.50	5.00	ОВЈЕСТ	SHDN a	N	WINTERIZE PUMP, LOCK RAMS, SECURE RIG, SDTM 3-22-04 H&M PRECISION WILL PUMP 100 GALLONS P163 DOWN TUBING, SHUT IN, LET SET TILL MONDAY
6 (LWK)	03/22/2004 06:00	07:00	1.00		PREWRK	MIMO a	N	ROAD CREW TO LOCATION.
6 (LWK)	03/22/2004 07:00	07:15	0.25		PREWRK	SAFE a	N	HELD SAFETY MTG W 5 RIG HANDS & RIG SUPERVISOR.
6 (LWK)	03/22/2004 07:15	10:30	3.25		OBJECT	TRIP a	N	TIH W TBG, DROP STD VALVE, TEST TBG EVERY 15 STDS TO 1500 PSI.
6 (LWK)	03/22/2004 10:30	11:15	0.75		ОВЈЕСТ	FISH a	N	RU TO FISH STD VALVE, ATTEMPT TO FISH W SND LINE, COULD NOT GET DWN, 10 STDS SHORT OF SEATING NIPPLE, POOH W OVERSHOT.
6 (LWK)	03/22/2004 11:15	14:00	2.75		OBJECT	TRIP a	N	TOOH W TBG, CHECK FOR BAD TBG, LD 4 JTS TBG.
6 (LWK)	03/22/2004 14:00	14:15	0.25		OBJECT	FISH a	N	RIH W OVERSHOT, FISHED STD VALVE, POOH W SAME.
6 (LWK)	03/22/2004 14:15	15:30	1.25		OBJECT	TRIP a		TIH W TBG, PU 4 ЛЗ TBG, LND 192 ЛЗ 2.375' TBG @ 5998.63' KB DEPTH.
6 (LWK)	03/22/2004 15:30	16:00	0.50		OBJECT	NUND a	N	NDBOP, RD FLOOR/EQUIPMENT, NU TBG HEAD.
6	03/22/2004	18:00	2.00	5.00	OBJECT	TRIP	N	RU TO RUN RODS/PUMP, RIH W PUMP/RODS,

(LWK)	16:00					а		SEAT PUMP, LOAD TBG W WATER. PSI TEST TO 1500 PSI, STROKE PUMP, SD.
6 (LWK)	03/22/2004 18:00	06:00	12.00	5.00	OBJECT	SHDN a	N	SDFN, LEFT WELL ON COMPRESSION.
7 (LWK)	03/23/2004 06:00	07:00	1.00		PREWRK	MIMO a	N	ROAD CREW TO LOCATION.
7 (LWK)	03/23/2004 07:00	07:15	0.25		PREWRK	SAFE a	11	HELD SAFETY MTG W 5 RIG HANDS & RIG SUPERVISOR.
7 (LWK)	03/23/2004 07:15	08:00	0.75	·	OBJECT	TRIP a		HANG PUMP OFF, INSTALL GUARD AROUND PUMP JACK, BEGAN WELL PUMPING, HAS GOOD PUMP ACTION.
7 (LWK)	03/23/2004 08:00	09:00	1.00		RDMO	RURD a	N	RDMO TJR #5, RLSD @ 09:00 HRS.
7 (LWK)	03/23/2004 09:00	06:00	21.00	,	OBJECT	SHDN a	N	WELL RETURNED TO PRODUCTION.

Global Intranet | Comments and Feedback | Legal Notice | Privacy Statement