

30-043-20954

Elm Ridge Resources, Inc.
Bonita Canyon #1
Sec. 23-T23N-R4W
San Juan, New Mexico

SLOPE TESTS

DEPTH

136
347
840
1026
1098
1160
1251
1335
1429
1554
1998
2245
2423
2641
2837
3139
3729
4237
4733
5290
5613
6231
7292

HOLE DEVIATION

1/2
3/4
4
4-1/4
4-3/4
3-3/4
3-3/4
2-3/4
2-3/4
1-3/4
1
3/4
1
1-1/4
1-1/4
1
3/4
1
3/4
3/4
3/4
1
1



State of New Mexico)

) SS
County of San Juan)

I, Trudy Grubelnik, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Trudy Grubelnik

Subscribed and sworn before me this 31st day of March, 2003.

Kinda R. Peltus

Notary Public

My commission Expires

Oct 8th, 2006