



**Key Energy Services, Inc.**

Four Corners Division  
5651 US Highway 64  
P.O. Box 900  
Farmington, NM 87499

Phone: 505-327-4935  
Fax: 505-327-4962

March 24, 2004

30-045-31757

Rig #43

M&G Drilling  
PO Box 9560  
Palm Springs, CA 92263

This is to certify that Key Energy Services, did run deviation surveys at the listed depths on your Graham 3-8 well in S3-T27N-R8W in San Juan County, New Mexico.


Depth	Deviation	Depth	Deviation
125'	¾°	2426'	1¼°
320'	¾°	2812'	1°
460'	¾°	3421'	1¼°
920'	1¼°	3911'	¾°
1449'	1¼°	4408'	¾°
1949'	1¼°	4889'	1°

To the best of my knowledge, I swear this information to be true.

Sincerely,

*Gary Miller*

Gary Miller  
District Drilling Manager



*Christina Allen*  
Notary Public



My commission expires:

*Dec 22 2007*